



2017 Livestock Evaluations

Eastern Regional Office



- Multiple Warning Letters
- Ecology funding

Direct tributary to ESA Steelhead stream




Multiple Letters



ESA
Steelhead
stream



Multiple Letters





Multiple Letters



Direct tributary to
ESA Steelhead stream



2016 Warning Letter



7.1



7.2

Multiple Letters



7.2



New Site



floodplain



Stream modification




- Multiple Letters
- 2016 Ecology Managers Site Visit



Spokane River
tributary

- Multiple complaints
- Existing contact





10.2

Multiple Letters



Tributary to lake

10.2

Tributary to lake



10.1

Multiple Letters



10.2

fence
CD project



Creek



New Site





Stream

• 2015 Letter





- Previously contacted

Stream



Inadequate Projects



manure

manure

CD project

- There is no vegetation to filter polluted run-off.
- To protect water quality, this site still needs work

Hotwire

Creek



- CD project
- Exclusion fence damaged, missing, and too close.
- Feeding and manure in riparian area.
- Damaged streambanks
- Water quality is still not protected



- Nearby residential area was flooded with sediment
- Order previously issued

Questions



2013



2015



2016



2017

