PREASSESSMENT SCREENING OIL SPILL REPORT FORM

| ERTS# | 712895 |
|---------------------------|--|
| Date of Incident: | 02/22/2022 |
| Potential Liable Party: | Robert L. Williams |
| Product Spilled: | Lube Oil/Motor Oil, Sheen |
| Spill Source: | ex-tug P/C Kokua (Recreational Vessel) |
| Oil Spill Size Estimate: | 69 gallons |
| Water Body Affected: | Puget Sound |
| Ecology Region: | NWRO |
| County: | Kitsap |
| Nearest City: | Kingston |
| Location of Spill: | President Point |
| Cause: | Inadequate Maintenance, Judgment, Wind |
| Ecology Responder: | Amanda Howe |
| Incident Summary: | On February 22, 2022, the P/C <i>Kokua</i> became stranded at President Point. The <i>Kokua</i> apparently drifted from its anchored location in Appletree Cove due to strong northerly winds. As the tide went out, the vessel would tip over and spill oil. Ecology and the USCG responded, and Ecology worked with the WDNR Derelict Vessel Program to remove the vessel from the beach. Based on oil recovery data provided by Global Diving and Salvage, an estimated 69 gallons of oil was recovered from the Puget Sound. As much as 100 gallons of diesel fuel was aboard the vessel at the time of the grounding. On March 7, 2022, Global Diving and Salvage brought in a crane barge to dismantle the <i>Kokua</i> in place. |